

SPARE PARTS					
Qty	Part Number	Stock Number	Description	Length	Wear Item
2	5AQ.41.062-C08	22.42.2000	Wear Strip mk 1042	361.0	Yes
2	5AQ.41.062-C09	3700AB	P10/2 Black	605.0	Yes
2	5AQ.41.062-D02	32T10/US	32T10 Timing Belt	1720.0	Yes
1	5AQ.41.062-D03	K002022020	Drive Shaft	863.0	Yes
2	47.02.0002		Coupling, 20x20, 310 in-lbs		Yes
4	2242CC0150		Lead-In ZRF-P 2010 A	150.0	Yes
2	8401DB0108		Drive Shaft P-2010		Yes
8	K101000428		6006-2RS Bearing		Yes
2	MGPM80-50Z		SMC Guided Cylinder		Yes
1	P25.40.001		#40 Roller Chain	400.0	Yes
1	P25.40.010		CONN. LINK, #40		Yes
4	P58.01.002		ZRF-P 2010 Flanged Pulley 28-T10		Yes
2	SP40B12-N-20		#40 Chain, 12T Sprocket, 20mm Bore		Yes

MACHINED PARTS TO BE FREE OF SHARP EDGES & BURS REMOVE ALL INK STAMPS, DECALS & BLEMISHES		Sheet size		mk North America, Inc. 105 Highland Park Drive. Bloomfield, CT 06002 Ph: 860.769.5500 www.mknorthamerica.com	
This document contains proprietary information which shall not be reproduced, transferred to other documents, disclosed to others, used for manufacturing or any other purpose without written permission of mk North America, Inc.		B		NORTH AMERICA, INC. mk a member of the mk Technology Group	
-All dimensions in millimeters unless otherwise specified-		Name	Date	Title: Spare Parts For 5AQ.41.062	
Assembly Tolerances:		Drawn	6/17/2024	Finish:	
Standard Tolerances:		Checked		Drawing No.	
0 - 1,000 mm: +/- 1 mm		Approved		Matl:	
1,001 - 3,000 mm: +/- 2 mm		Revision		-Do not scale drawing-	
3,001 - 5,000 mm: +/- 5 mm				Sheet of 1	
5,001 - 10,000 mm: +/- 10 mm					
CTL Tolerance: +/- .5mm					